

R.N.G.P.I.T, Bardoli
Electrical Engineering Department

Subject: Electrical Machine-I

Prepared By:
Dr. Shaikh Mohammed Suhel

Prepared By:

- NAME: DR. SHAIKH MOHAMMED SUHEL
(ASSISTANT PROFESSOR RNGPIT, SURAT)
- FORMER ASSISTANT PROFESSOR IN SCET, SNPIT&RC, VIT
- QUALIFICATION: PHD (POWER- ELECTRONICS & DRIVES, NIT, SURAT), M.TECH (INDUSTRIAL ELECTRONICS, NIT-SURAT), GATE, B.E. (ELECTRICAL ENGINEERING., VNSGU-SURAT).
- EXPERIENCE: 13 YEARS.

Subject: Electrical Machine-I

- This Lecture contains
 - Basic Principle of Transformer
 - Phasor Diagram of Transformer

Syllabus

Transformers:


Review of construction and working principle of single-phase and three-phase transformers, equivalent circuit, phasor diagram, voltage regulation, losses and efficiency.

Testing - open circuit and short circuit tests, polarity test, back-to-back test, separation of hysteresis and eddy current losses

Three-phase transformer - construction, types of connection and their comparative features, Vector groups, Parallel operation of single-phase and three-phase transformers, Autotransformers - construction, principle, applications and comparison with two winding transformer, Magnetizing current, effect of nonlinear B-H curve of magnetic core material, harmonics in magnetization current, Phase conversion - Scott connection, three-phase to six-phase conversion, Tap-changing transformers - No-load and on-load tap-changing of transformers, Three-winding transformers. Cooling of transformers.

- Problem associated with High voltage generation or utilization

If generator voltage increases then amount of insulation is also increases



- *Application of transformer*



High Power Transmission

Impedance matching transformer

Isolation Transformer

High frequency transformer

Auto transformer, Current Transformer, Pulse transformer




- **Transformer:** Transfer electrical energy from one electrical circuit to another without electrical connection between two circuit

- This electrical circuit are magnetically coupled through a common core.

- **Principle:** Electromagnetic induction



- Voltage, Power , frequency?






- *Emf induced in the transformer is statically induced emf*
- *Statically induced emf= conductor is stationary and field is varying with the time*
- *Faradays second law:*

$E_s \propto$ rate of change of flux linkages

$$E_s \propto -\frac{d}{dt}(N\phi) \quad E_s \propto -N \frac{d\phi}{dt}$$



- Negative sign is due to Lenz's law
- Right hand thumb rule




- *Statically induced emf type:*
 - 1) *self induced emf and*
 - 2) *mutually induced emf*


- *Self induced emf*

- *Mutually induced emf*

- *When two coils are inductively coupled & if current in one coil changed uniformly then emf gets induced in the other coil*



- *Emf induced in the primary of transformer is self induced emf*
- *Emf induced in the secondary is due to mutual inductance*



- *EMF equation of Transformer:*

- $N_1 =$ No. of turns in primary

- $N_2 =$ No. of turns in secondary

- $\Phi_m =$ maximum flux in the core $= B_m \cdot A$


- $F =$ frequency of ac input

$$\text{Average rate of change of flux} = \frac{\phi_m}{1/4f} = 4f\phi_m \text{ wb/s or volt}$$

$$\text{Average emf/turn} = 4f\phi_m \text{ volt}$$

$$\text{Form factor} = \frac{\text{RMS value}}{\text{Mean value}} = 1.11$$

$$\text{RMS value of emf / turn} = 4.44f\phi_m \text{ volt}$$



RMS value of emf induced in primary $= 4.44f\phi_m N_1$ volt

RMS value of emf induced in secondary $= 4.44f\phi_m N_2$ volt

- *EMF equation of Transformer:*

$$E_1 = 4.44 f \phi_m N_1 \text{ volt}$$


$$E_2 = 4.44 f \phi_m N_2 \text{ volt}$$

$$\frac{E_2}{E_1} = \frac{N_2}{N_1}$$


For an ideal transformer input VA=output VA

$$V_1 I_1 = V_2 I_2$$


$$\frac{I_2}{I_1} = \frac{V_1}{V_2} = \frac{1}{K}$$



- A 25 KVA transformer has 500 turns on the primary and 50 turns on the secondary windings. The primary is connected to 3000-V, 50 Hz supply. Find the full load primary and secondary currents, the secondary emf and the maximum flux in the core. Neglect leakage drop and no load primary current.



- *Ideal Transformer*
- *No Ohmic resistance, No Loss*
- *Permeability of the transformer core is infinite (no magnetizing current required to established the flux)*
- *Hysteresis & eddy current losses are zero*
- *No magnetic leakage ($X1=X2=0$)*
- *Magnetization curve is linear*



- *Transformer with finite permeability*
- *magnetizing component of current*

$$i_{\mu} = I_m \sin \omega t$$

$$\text{Primary MMF} = N_1 \cdot i_{\mu}$$

$$\text{Primary MMF} = N_1 \cdot i_m \sin \omega t$$

$$\text{Flux} = \frac{\text{MMF}}{\text{Reluctance}} = \frac{N_1 \cdot i_m \sin \omega t}{R} = \phi_m \sin \omega t$$

$$E_1 = - N_1 \frac{d\phi}{dt} = - N_1 \frac{d}{dt} \phi_m \sin \omega t$$

$$E_1 = N_1 \omega \phi_m \sin\left(\omega t - \frac{\pi}{2}\right)$$

- The primary induce emf lags the flux by 90°


$$E_1 = N_1 \omega \phi_m \sin\left(\omega t - \frac{\pi}{2}\right)$$

$$E_{1\max} = N_1 \omega \phi_m$$

$$E_1 = \frac{E_{1\max}}{\sqrt{2}} = N_1 2\pi f \phi_m / \sqrt{2}$$

$$E_1 = 4.44 N_1 f \phi_m$$

$$E_1 = 4.44 N_1 f B_m A$$



$$E_2 = -N_2 \frac{d\phi}{dt}$$

$$E_2 = 4.44 N_2 f B_m A$$

$$\frac{E_1}{N_1} = 4.44 f B_m A = \frac{E_2}{N_2}$$




$$\frac{E_2}{E_1} = \frac{N_2}{N_1} = k$$

- Phasor diagram


$$\phi = \phi_m \sin \omega t$$

$$i_u = I_m \sin \omega t$$

$$E_1 = N_1 \omega \phi_m \sin(\omega t - \frac{\pi}{2})$$



- Transformer with iron loss



- Magnetizing component of current i_{μ}
- Iron loss component of current i_{ω}
- No load current is the summation of these two components



$$\overline{i_o} = \overline{i_{\mu}} + \overline{i_{\omega}}$$

- Phasor diagram with iron loss

$$\phi = \phi_m \sin \omega t$$

$$i_\mu = I_m \sin \omega t \quad \bar{i}_o = \bar{i}_\mu + \bar{i}_\omega$$

$$E_1 = N_1 \omega \phi_m \sin(\omega t - \frac{\pi}{2})$$



- Phasor diagram with Resistive load

$$\phi = \phi_m \sin \omega t \quad \bar{i}_o = \bar{i}_\mu + \bar{i}_\omega$$


$$i_\mu = I_m \sin \omega t \quad \bar{i}_1 = \bar{i}_0 + \bar{i}_2'$$

$$E_1 = N_1 \omega \phi_m \sin(\omega t - \frac{\pi}{2})$$

$$\phi_2 = \phi_2'$$

$$N_2 I_2 = N_1 I_2'$$

$$I_2' = K I_2$$



- Phasor diagram with Resistive load

$$\phi = \phi_m \sin \omega t \quad \bar{i}_o = \bar{i}_\mu + \bar{i}_\omega$$


$$i_\mu = I_m \sin \omega t \quad \bar{i}_1 = \bar{i}_0 + \bar{i}_2'$$

$$E_1 = N_1 \omega \phi_m \sin(\omega t - \frac{\pi}{2})$$

$$\phi_2 = \phi_2'$$

$$N_2 I_2 = N_1 I_2'$$

$$I_2' = K I_2$$





- Phasor diagram with Inductive load

$$\phi = \phi_m \sin \omega t \quad \bar{i}_o = \bar{i}_\mu + \bar{i}_\omega$$

$$i_\mu = I_m \sin \omega t \quad \bar{i}_1 = \bar{i}_0 + \bar{i}'_2$$

$$E_1 = N_1 \omega \phi_m \sin(\omega t - \frac{\pi}{2})$$



- Transformer with winding Resistance

$$\phi = \phi_m \sin \omega t \quad \bar{i}_o = \bar{i}_\mu + \bar{i}_\omega$$


$$i_\mu = I_m \sin \omega t \quad \bar{i}_1 = \bar{i}_o + \bar{i}_2'$$

$$E_1 = N_1 \omega \phi_m \sin(\omega t - \frac{\pi}{2})$$

$$\phi_2 = \phi_2'$$

$$N_2 I_2 = N_1 I_2'$$

$$I_2' = K I_2$$






➤ Transformer phasor diagram

Including the resistance and inductances of the windings:


$$\bar{V}_1 = -\bar{E}_1 + \bar{I}_1 R_1 + j\bar{I}_1 X_1$$

$$\bar{E}_2 = \bar{V}_2 + \bar{I}_2 R_2 + j\bar{I}_2 X_2$$





➤ Transformer phasor diagram

Including the resistance and inductances of the windings:



$$\bar{V}_1 = -\bar{E}_1 + \bar{I}_1 R_1 + j\bar{I}_1 X_1$$

$$\bar{E}_2 = \bar{V}_2 + \bar{I}_2 R_2 + j\bar{I}_2 X_2$$



THANK YOU